



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Production

Technical Specification 5.6.8

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

TEL (623) 393-6116
FAX (623) 393-6077

192-01111-WEI/TNW/DFH
October 29, 2002

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528
Special Report 1-SR-2002-002**

Attached please find Special Report 1-SR-2002-002 prepared and submitted pursuant to Technical Specifications (TS) Reporting Requirement 5.6.8. This report discusses steam generator tube plugging in Unit 1. Pursuant to Technical Specification 5.6.8, the complete results of the steam generator tube inservice inspection will be submitted by October 21, 2003. Copies of the Special Report are being forwarded to the Regional Administrator, NRC Region IV and the PVNGS Resident Inspector.

No commitments are being made to the NRC by this letter.

If you have any questions, please contact Thomas N. Weber at (623) 393-5764.

Sincerely,

WEI/TNW/DFH/kg

Attachment

cc: E. W. Merschoff (all with attachment)
J. N. Donohew
M. B. Fields
N. L. Salgado

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

A047

Attachment

Special Report No. 1-SR-2002-002

Palo Verde Nuclear Generating Station Unit 1

Steam Generator Tube Plugging

Docket No. STN 50-528

Special Report No. 1-SR-2002-002

This Special Report is being provided pursuant to Palo Verde Unit 1 Technical Specifications (TS) Reporting Requirement 5.6.8 to report the number of steam generator tubes plugged and/or repaired as a result of inservice inspection activities. On October 21, 2002, Unit 1 was defueled during a refueling outage when an inservice inspection of both steam generators was completed. The inspection resulted in the plugging of 236 tubes in Steam Generator No. 1 and 234 tubes in Steam Generator No. 2.

Pursuant to Technical Specification 5.6.8, the complete results of the steam generator tube inservice inspection will be submitted by October 21, 2003.